



Report No.: EED32P81346801 Page 50 of 62

7 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Below 1GHz)(close up)














Report No.: EED32P81346801



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz) There are absorbing materials under the ground.















Report No.: EED32P81346801







Conducted Emissions Test Setup-2(close up)









