

Report No.: LGT23L104




Appendix - Internal Photographs of EUT Constructional Details

Model: SM-S004-001 Photo 1



Photo 2







Report No.: LGT23L104

Photo 3




Photo 4








Photo 5

