



Report No.: EED32Q80387801 Page 29 of 38

## **7 PHOTOGRAPHS OF TEST SETUP**



Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-2(Below 1GHz)
















Report No.: EED32Q80387801





Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 18GHz)















Report No.: EED32Q80387801





Radiated spurious emission Test Setup-5(Above 41GHz)



Radiated spurious emission Test Setup-6(close up photo)













Report No.: EED32Q80387801





