


Report No.: EED32Q80555301 Page 36 of 47

6 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-2(Below 1GHz)















Report No.: EED32Q80555301





Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 18GHz)
















Report No.: EED32Q80555301





Radiated spurious emission Test Setup-5(Above 41GHz)



Radiated spurious emission Test Setup-6 There are absorbing materials under the ground.









