
SAMSUNG

Mobile Phone : GT-I9200

APPENDIX

- Test Setup and EUT photography -

This report must not be reproduced, except in full, without written permission from CS & Environment center. Form No.: SRA-TRF-46/0




Mobile Phone : GT-I9200

1. Photograph of Test Setup




[Conducted Disturbance – Front]



[Conducted Disturbance – Rear]


-2/4-

This report must not be reproduced, except in full, without written permission from CS & Environment center. Form No.: SRA-TRF-46/0



Project No. : LBE20131992

Mobile Phone : GT-I9200




[Radiated Disturbance for Below 1 GHz – Front]



[Radiated Disturbance for Below 1 GHz – Rear]


-3/4-

This report must not be reproduced, except in full, without written permission from CS & Environment center. Form No.: SRA-TRF-46/0




Project No. : LBE20131992

Mobile Phone : GT-I9200



[Radiated Disturbance for Above 1 GHz – Front]



[Radiated Disturbance for Above 1 GHz – Rear]

-4/4-

This report must not be reproduced, except in full, without written permission from CS & Environment center. Form No.: SRA-TRF-46/0