Mobile Phone : SM-A125F/DSN


APPENDIX

– Test Setup and EUT photographs –


Mobile Phone : SM-A125F/DSN

1. Photograph of Test Setup

□ Conducted Disturbance



[Mode 1 - 4 : Front]




[Mode 1 - 4 : Rear]

This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/11

-2/9-

Mobile Phone : SM-A125F/DSN



[Mode 5 : Front]




[Mode 5 : Rear]

This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/11

-3/9-

Mobile Phone : SM-A125F/DSN



□ Radiated Disturbance for Below 1 GHz

[Mode 1 : Front]




[Mode 1 : Rear]

-4/9-

Mobile Phone : SM-A125F/DSN



[Mode 2 - 4 : Front]



[Mode 2 - 4 : Rear]

-5/9-

Mobile Phone : SM-A125F/DSN



[Mode 5 : Front]




[Mode 5 : Rear]

This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/11

-6/9-

Mobile Phone : SM-A125F/DSN

□ Radiated Disturbance for Above 1 GHz



[Mode 1 : Front]



[Mode 1 : Rear]

-7/9-

Mobile Phone : SM-A125F/DSN




[Mode 2 - 4 : Front]



[Mode 2 - 4 : Rear]

-8/9-

Mobile Phone : SM-A125F/DSN



[Mode 5 : Front]



[Mode 5 : Rear]