Mobile Phone : SM-A146M/DS


# **APPENDIX**

## – Test Setup and EUT photographs –


Mobile Phone : SM-A146M/DS

1. Photograph of Test Setup

### □ Conducted Disturbance



[ Mode 1 - 3 : Front ]




[Mode 1 - 3 : Rear]

This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/11

-2/9-

Mobile Phone : SM-A146M/DS



[Mode 4 : Front]



[Mode 4 : Rear]


This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/11

-3/9-

Mobile Phone : SM-A146M/DS

### □ Radiated Disturbance for Below 1 GHz


[Mode 1 : Front]



[Mode 1 : Rear]

-4/9-

Mobile Phone : SM-A146M/DS



[ Mode 2 - 3 : Front ]



[Mode 2 - 3 : Rear]

This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/11

-5/9-

Mobile Phone : SM-A146M/DS



[Mode 4 : Front]




[Mode 4 : Rear]

This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/11


-6/9-

Mobile Phone : SM-A146M/DS

### □ Radiated Disturbance for Above 1 GHz



[Mode 1 : Front]




[Mode 1 : Rear]

-7/9-

Mobile Phone : SM-A146M/DS




[ Mode 2 - 3 : Front ]




[Mode 2 - 3 : Rear]

-8/9-

Mobile Phone : SM-A146M/DS



[Mode 4 : Front]



[Mode 4 : Rear]

-9/9-