
APPENDIX

– Test Setup and EUT photographs –

1. Photograph of Test Setup

□ Conducted Disturbance




[Mode 1 - 4 : Front]



[Mode 1 - 4 : Rear]

-2/9-

Mobile Phone : SM-A205G/DS




[Mode 5 : Front]




[Mode 5 : Rear]

-3/9-

□ Radiated Disturbance for Below




[Mode 1 : Front]




[Mode 1 : Rear]

-4/9-

Mobile Phone : SM-A205G/DS









[Mode 2 - 4 : Rear]

-5/9-

Mobile Phone : SM-A205G/DS



[Mode 5 : Front]





[Mode 5 : Rear]

-6/9-



□ Radiated Disturbance for Above 1 GHz







[Mode 1 : Rear]

-7/9-

Mobile Phone : SM-A205G/DS









[Mode 2 - 4 : Rear]

-8/9-

Mobile Phone : SM-A205G/DS



[Mode 5 : Front]



[Mode 5 : Rear]

-9/9-