# **APPENDIX**

# – Test Setup and EUT photographs –

1. Photograph of Test Setup

## □ Conducted Disturbance




[ Mode 1 – 4 : Front ]



[ Mode 1 – 4 : Rear ]

-2/9-

Mobile Phone: SM-A315G/DSL




[Mode 5 : Front]




[Mode 5 : Rear]

-3/9-

# □ Radiated Disturbance for Below 1 GHz




[Mode 1 : Front]




[Mode 1 : Rear]

-4/9-

Mobile Phone: SM-A315G/DSL



[ Mode 2 - 4 : Front ]




[ Mode 2 - 4 : Rear ]

-5/9-

Mobile Phone: SM-A315G/DSL




[Mode 5 : Front]




[Mode 5 : Rear]

-6/9-



### □ Radiated Disturbance for Above 1 GHz


[Mode 1 : Front]



[Mode 1 : Rear]

-7/9-

Mobile Phone: SM-A315G/DSL




[ Mode 2 - 4 : Front ]



[ Mode 2 - 4 : Rear ]

-8/9-

Mobile Phone: SM-A315G/DSL



[Mode 5 : Rear]

-9/9-