
APPENDIX

– Test Setup and EUT photographs –

1. Photograph of Test Setup

□ Conducted Disturbance



[Mode 1 - 3 : Front]




[Mode 1 - 3 : Rear]

This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/11

-2/9-

Mobile Phone : SCG08



[Mode 4 : Front]



[Mode 4 : Rear]


This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/11

-3/9-



□ Radiated Disturbance for Below 1 GHz


[Mode 1 : Front]




[Mode 1 : Rear]

-4/9-

Mobile Phone : SCG08




[Mode 2 - 3 : Front]



[Mode 2 - 3 : Rear]

Mobile Phone : SCG08



[Mode 4 : Front]



[Mode 4 : Rear]

This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/11

-6/9-



□ Radiated Disturbance for Above 1 GHz


[Mode 1 : Front]




[Mode 1 : Rear]

-7/9-

Mobile Phone : SCG08




[Mode 2 - 3 : Front]



[Mode 2 - 3 : Rear]

-8/9-

Mobile Phone : SCG08



[Mode 4 : Front]



[Mode 4 : Rear]

-9/9-