
APPENDIX

- Test Setup and EUT photographs -

1. Photograph of Test Setup

□ Conducted Disturbance




[Mode 1 – 4 : Front]



[Mode 1 – 4 : Rear]

-2/9-

Mobile Phone: SM-A705GM/DS




[Mode 5 : Front]



[Mode 5 : Rear]

-3/9-

$\hfill\square$ Radiated Disturbance for Below 1 GHz




[Mode 1 : Front]




[Mode 1 : Rear]

-4/9-

Mobile Phone: SM-A705GM/DS



[Mode 2 - 4 : Front]




[Mode 2 - 4 : Rear]

-5/9-

Mobile Phone: SM-A705GM/DS




[Mode 5 : Front]




[Mode 5 : Rear]

-6/9-

□ Radiated Disturbance for Above 1 GHz




[Mode 1 : Front]




[Mode 1 : Rear]

-7/9-

Mobile Phone: SM-A705GM/DS



[Mode 2 - 4 : Front]



[Mode 2 - 4 : Rear]

-8/9-

Mobile Phone: SM-A705GM/DS



[Mode 5 : Front]



[Mode 5 : Rear]

-9/9-