Mobile Phone : SM-A705YN


APPENDIX

– Test Setup and EUT photographs –

Mobile Phone : SM-A705YN

1. Photograph of Test Setup

□ Conducted Disturbance




[Mode 1 – 4 : Front]




[Mode 1 – 4 : Rear]

-2/9-

Mobile Phone : SM-A705YN




[Mode 5 : Front]



[Mode 5 : Rear]

Mobile Phone : SM-A705YN

□ Radiated Disturbance for Below




[Mode 1 : Front]



[Mode 1 : Rear]

-4/9-

Mobile Phone : SM-A705YN



[Mode 2 - 4 : Front]




[Mode 2 - 4 : Rear]

This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/7

-5/9**-**

Mobile Phone : SM-A705YN



[Mode 5 : Front]




[Mode 5 : Rear]

This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/7


-6/9-

Mobile Phone : SM-A705YN

□ Radiated Disturbance for Above 1 GHz




[Mode 1 : Front]




[Mode 1 : Rear]

-7/9-

Mobile Phone : SM-A705YN



[Mode 2 - 4 : Front]




[Mode 2 - 4 : Rear]

This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/7

-8/9**-**

Mobile Phone : SM-A705YN



[Mode 5 : Front]



[Mode 5 : Rear]

-9/9-