
# **APPENDIX**

# - Test Setup and EUT photographs -

1. Photograph of Test Setup

## □ Conducted Disturbance




[ Mode 1 – 3 : Front ]



[ Mode 1 – 3 : Rear ]

-2/9-

Mobile Phone: SM-A805F/DS




[Mode 4 : Front]




[Mode 4 : Rear]

-3/9-

# $\hfill\square$ Radiated Disturbance for Below 1 GHz








[Mode 1 – 3 : Rear]

-4/9-

Mobile Phone: SM-A805F/DS




[Mode 4 : Front]




[Mode 4 : Rear]

-5/9-

Mobile Phone: SM-A805F/DS



[Mode 5 : Front]




[Mode 5 : Rear]

-6/9-

# □ Radiated Disturbance for Above 1 GHz




[ Mode 1 – 3 : Front ]




[Mode 1 – 3 : Rear]

-7/9-

Mobile Phone: SM-A805F/DS




[Mode 4 : Front]




[Mode 4 : Rear]

-8/9-

Mobile Phone: SM-A805F/DS



[Mode 5 : Front]



[Mode 5 : Rear]

-9/9-