Project No.: LBE20200802

Mobile Phone: SM-G781U

# **APPENDIX**

Test Setup and EUT photographs –


Form No.: SRA-TRF-46/11

Project No.: LBE20200802


Mobile Phone: SM-G781U

# 1. Photograph of Test Setup

## ☐ Conducted Disturbance




[ Mode 1 - 4 : Front ]



[ Mode 1 - 4 : Rear ]



[ Mode 5 : Front ]




[ Mode 5 : Rear ]

### ☐ Radiated Disturbance for Below 1 GHz




[ Mode 1 - 2 : Front ]




[ Mode 1 - 2 : Rear ]




[ Mode 3 - 4 : Front ]



[ Mode 3 - 4 : Rear ]




[ Mode 5 : Front ]



[ Mode 5 : Rear ]



[ Mode 6 : Front ]




[ Mode 6 : Rear ]

### ☐ Radiated Disturbance for Above 1 GHz




[ Mode 1 - 2 : Front ]




[ Mode 1 - 2 : Rear ]




[ Mode 3 - 4 : Front ]




[ Mode 3 - 4 : Rear ]




[ Mode 5 : Front ]



[ Mode 5 : Rear ]



[ Mode 6 : Front ]



[ Mode 6 : Rear ]