Project No.: LBE20181984

Mobile Phone: SM-G975N

APPENDIX

Test Setup and EUT photographs –

Project No.: LBE20181984

Mobile Phone : SM-G975N

1. Photograph of Test Setup

□ Conducted Disturbance




[Mode 1 – 4 : Front]




[Mode 1 – 4 : Rear]

Project No.: LBE20181984

Mobile Phone : SM-G975N




[Mode 5 : Front]




[Mode 5 : Rear]


☐ Radiated Disturbance for Below




[Mode 1 : Front]




[Mode 1 : Rear]




[Mode 2 : Front]



[Mode 2 : Rear]




[Mode 3 : Front]




[Mode 3 : Rear]




[Mode 4 : Front]



[Mode 4 : Rear]




[Mode 5 : Front]




[Mode 5 : Rear]


☐ Radiated Disturbance for Above 1 GHz




[Mode 1 : Front]




[Mode 1 : Rear]




[Mode 2 : Front]




[Mode 2 : Rear]




[Mode 3 : Front]



[Mode 3 : Rear]



[Mode 4 : Front]



[Mode 4 : Rear]



[Mode 5 : Front]



[Mode 5 : Rear]