


# APPENDIX

## – Test Setup and EUT photographs –

## 1. Photograph of Test Setup


### Conducted Disturbance




[ Mode 1 – 3 : Front ]



[ Mode 1 – 3 : Rear ]



**[ Mode 4 : Front ]**




**[ Mode 4 : Rear ]**

Radiated Disturbance for Below 1 GHz




[ Mode 1 : Front ]



[ Mode 1 : Rear ]



**[ Mode 2 : Front ]**




**[ Mode 2 : Rear ]**




**[ Mode 3 : Front ]**




**[ Mode 3 : Rear ]**




**[ Mode 4 : Front ]**



**[ Mode 4 : Rear ]**




**[ Mode 5 : Front ]**




**[ Mode 5 : Rear ]**

Radiated Disturbance for Above 1 GHz




**[ Mode 1 : Front ]**



**[ Mode 1 : Rear ]**




**[ Mode 2 : Front ]**




**[ Mode 2 : Rear ]**




**[ Mode 3 : Front ]**




**[ Mode 3 : Rear ]**



**[ Mode 4 : Front ]**



**[ Mode 4 : Rear ]**



**[ Mode 5 : Front ]**



**[ Mode 5 : Rear ]**