
Mobile Phone: SM-J737T

# **APPENDIX**


## - Test Setup and EUT photographs -

This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/5 Mobile Phone: SM-J737T

### 1. Photograph of Test Setup



## [ Conducted Disturbance – Front ]




[ Conducted Disturbance – Rear ]

-2/4-


This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/5

#### Project No. : LBE20180847

Mobile Phone: SM-J737T



[Radiated Disturbance for Below 1 GHz – Front]



[Radiated Disturbance for Below 1 GHz – Rear]

This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/5


-3/4-

#### Project No. : LBE20180847

Mobile Phone: SM-J737T



[Radiated Disturbance for Above 1 GHz – Front]



[Radiated Disturbance for Above 1 GHz – Rear]

-4/4-

This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/5