APPENDIX

– Test Setup and EUT photographs –

1. Photograph of Test Setup

□ Conducted Disturbance



[Mode 1 – 4 : Front]



[Mode 1 – 4 : Rear]


This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/7

-2/9-

Mobile Phone: SM-M205F/DS



[Mode 5 : Front]




[Mode 5 : Rear]


This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/7

-3/9-

□ Radiated Disturbance for Below 1 GHz



[Mode 1 : Front]



[Mode 1 : Rear]


This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/7

-4/9-

Mobile Phone: SM-M205F/DS



[Mode 2 – 4 : Front]




[Mode 2 – 4 : Rear]

This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/7

-5/9**-**

Mobile Phone: SM-M205F/DS




[Mode 5 : Front]



[Mode 5 : Rear]


This report must not be reproduced, except in full, without written permission from Global CS Center. Form No.: SRA-TRF-46/7

-6/9-




$\hfill\square$ Radiated Disturbance for Above 1 GHz

[Mode 1 : Front]




[Mode 1 : Rear]

Mobile Phone: SM-M205F/DS



[Mode 2 – 4 : Front]




[Mode 2 – 4 : Rear]

Mobile Phone: SM-M205F/DS



[Mode 5 : Front]



[Mode 5 : Rear]