

HCT Co., Ltd. 74, Seoicheon-ro 578beon-gil, Majang-myeon, Icheon-si, Gyeonggi-do, 17383 KOREA Tel. +82 31 634 6300 Fax. +82 31 645 6401

Appendix A: Test Setup Photo FCC ID A3LSMX818U

 File No.

 HCT-RF-2305-FC036-P
 HCT-RF-2305-FC037-P

 HCT-RF-2305-FC038-P
 HCT-RF-2305-FC039-P

 HCT-RF-2305-FC040-P
 HCT-RF-2305-FC041-P

 HCT-RF-2305-FC042-P
 HCT-RF-2305-FC043-P

 HCT-RF-2305-FC044-P
 HCT-RF-2305-FC043-P

REVISION HISTORY


The revision history for this document is shown in table.

Revision No.	Date of Issue	Description
0	May 09, 2023	Initial Release





1. Radiated Test Setup Photo

Radiated spurious emissions & Restricted Band Edge (Above 1 GHz)










































Radiated spurious emissions (Below 1GHz)

































WPS Radiated Test Setup Photo for










FCC ID: A3LSMX818U






FCC ID: A3LSMX818U



















































2. Conducted Test Setup Photo








3. DFS Test Setup Photo








4. AC Power Line Conducted Test Setup Photo







AC PowerLine Conducted Test WPS(S-pen) Setup Photo





5. Contention Based Protocol

