

Report No.: 4790101669

Incident Power Density test Setup Photo


Rear of the DUT




Front of the DUT











SAR test Setup Photo

Please refer to 4790101669-S1 FCC Report SAR App A_Photos & Ant. Locations.

Antenna Dimensions & Separation Distances

(Antennas and wireless bands were indicated only those applied to Power Density test.)

- ① WIFI 1 2.4G/5G/6G
- ② WIFI 2 2.4G/5G/6G

