Appendix D. SAR Test Setup Photos

Body Exposure Condition



Front at 5 mm

Back at 5 mm

Report No.: FA140144



Left Side at 5 mm

Right Side at 5 mm



Top Side at 5 mm



Bottom Side at 5 mm

TEL: 886-3-327-3456 Page: D1 of D1
FAX: 886-3-328-4978 Issued Date: Aug. 25, 2021

Form version: 200414