




**Product: Bose A94412568** 

**Test Setup Photos:** 

















#### **Radiated emissions**

### X-Axis









# Design Compliance Engineering – Analysis

## **Y-Axis**











### **Z-Axis**









Design Compliance Engineering – Analysis

Conducted RF measurements using spectrum analyzer.





Location of test points for conducted RF measurement













