


Napco Security PDL 3000


Test #319-00



Rear of Electronic control housing when removed from door

Napco Security PDL 3000


Test #319-00



Rear of Electronics Housing with cover removed

Napco Security PDL 3000


Test #319-00



Back side of Main Circuit Board

Napco Security PDL 3000


Test #319-00



Front of the Main Circuit Board

Napco Security PDL 3000


Test #319-00



Front of Tx PCB

Napco Security PDL 3000

Test #319-00



Rear of Tx PCB

Napco Security PDL 3000


Test #319-00



Antenna and leads viewed from inside the housing

Napco Security PDL 3000


Test #319-00



Antenna

Napco Security PDL 3000

Test #319-00



Rear of the Keypad

Napco Security PDL 3000

Test #319-00



Front of Keypad