

Date of issue: 10 June 2011

# Photographs of Furuno Radar Sensor DRS6A with Transceiver RTR-093A

### 1 Internal View

1.1 Inside View (with Top cover opened, showing Scanner Motor (upper) and Transceiver RTR-093A (lower))





Date of issue: 10 June 2011

# 1.2 Transceiver Top View





Date of issue: 10 June 2011


# 1.3 Transceiver Right Side View





Date of issue: 10 June 2011


1.4 Transceiver Top View (with Shield-cover removed, showing MD Board 03P9450 (upper) and PWR Board 03P9452 (lower))





Date of issue: 10 June 2011

# 1.5 Transceiver Right Side View (with Shield-cover removed, showing Magnetron MAF1422B)





Date of issue: 10 June 2011


# Circulator 1.6 Transceiver Rear side View Limiter **Filter Isolator**

Magnetron



Date of issue: 10 June 2011

### 1.7 Transceiver Bottom View





Date of issue: 10 June 2011

# 1.8 Transceiver Bottom View (with Shield-cover removed)





Date of issue: 10 June 2011

1.9 Transceiver Bottom View (with shield-covers removed, showing SPU Board 03P9455 (upper) and NMEA2000 Board 03P9462 (lower))

