
6. Photographs of test setup

The following photographs show the arrangement of the worst case.


6.1. AC Power-line Conducted Emissions Measurement Photo(s)




6.2. Antenna-port Conducted Measurements Photo(s)

Maximum Peak Conducted Output Power


Others





Project No: JB-Z0418

6.3. Radiated Spurious Emissions Measurement Photo(s)








 $1\,\mathrm{GHz}$ - $25\,\mathrm{GHz}$



in order to place for each axis.



<EUT Zoom>

The antenna was tested with attached to supporting jig that does not affect EMC characteristic

