


## 6. Photographs of test setup


The following photographs show the arrangement of the worst case.

### 6.1. AC Power-line Conducted Emissions Photo(s)




### 6.2. Antenna-port Conducted Measurements Photo(s)





Maximum Conducted Output Power



Others




### 6.3. Radiated Spurious Emissions Photo(s)




<EUT Axis>

X



Y



Z



The antenna was tested with attached to supporting jig that does not affect EMC characteristic in order to place for each axis.

<EUT Zoom>

