



Internal Photo 1: Unit Partially Disassemble-1




Internal Photo 2: Unit Partially Disassemble-2




Internal Photo 3: Camera Unit Disassembled




Internal Photo 4: Display Part and Camera Unit Disassembled




Internal Photo 5: Board-A Side-A




Internal Photo 6: : Board-A Side-B




Internal Photo 7: Board-B Side-A




Internal Photo 8: Board-B Side-B



Internal Photo 9: Bluetooth Module Side-A




Internal Photo 10: Bluetooth Module Side-B




Internal Photo 11: Bluetooth Module Location



Internal Photo 12: Bluetooth Module Shield Cover Removed



Internal Photo 13: Antenna Module Side-A



Internal Photo 14: Antenna Module Side-B