

APPENDIX 3: Photographs of Test Setup

Conducted Emission




Photo 1



Photo 2

Radiated Spurious Emission


Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)




Pre-check of Worst Case Position


EUT
X-axis




Antenna
X-axis



Y-axis




Y-axis



Z-axis




Z-axis




Pre-check of Worst Case Position

Antenna cable

100 mm



800 mm



Antenna Terminal Conducted Tests




Photo 1




Photo 2

End of Report