

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

Radiated Spurious Emission




Photo 3





Photo 4

Worst Case Position


EUT (Left)

X-axis




EUT (Left)


X-axis




Y-axis




Y-axis



Z-axis



Z-axis



Antenna Terminal Conducted Tests



Photo 1




Photo 2

End of Report