

Annex A: Photographs of the Test Set-up

Photo 1: Radiated Emission




Photo 2: Radiated Emission



2020-11-09 Page 1 of 5



Photo 3: Conducted Emission



2020-11-09 Page 2 of 5

Test report no.: 1-0932/20-01-05



Annex B: External Photographs of the EUT

Photo 1:



Photo 2:



2020-11-09 Page 3 of 5

Test report no.: 1-0932/20-01-05



Annex C: Internal Photographs of the EUT

Photo 1:





Photo 2:




2020-11-09 Page 4 of 5

Test report no.: 1-0932/20-01-05



Photo 3:



2020-11-09 Page 5 of 5