

**APPENDIX 3: Photographs of test setup**


**Conducted Emission**




## Radiated Spurious Emission



Rear (below 1 GHz)



Rear (above 1 GHz)



## Pre-check of Worst Case Position

**X-axis**



**Y-axis**



**Z-axis**



**End of Report**