


### APPENDIX 3: Photographs of test setup

#### Radiated Spurious Emission


Front



Rear (Below 1 GHz)



Rear (Above 1 GHz)



### Pre-check of Worst Case Position

X-axis



Y-axis



Z-axis



**End of Report**

---

**UL Japan, Inc.**

**Shonan EMC Lab.**

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400

Facsimile : +81 463 50 6401