











PHOTOGRAPHS OF TEST SET UP

Figure 1 - Radiated Disturbance - Below 1 GHz



Figure 2 Radiated Disturbance - Above 1 GHz







Apple Inc, Model No A2681





Figure 3 Radiated Disturbance - Above 1 GHz



Figure 4 - Conducted Disturbance at Mains Terminals

