



KTL Dallas, Inc.

Dallas Headquarters:

802 N. Kealy
Lewisville, TX 75057
Tel: (972) 436-9600
Fax: (972) 436-2667

Test Plot: Occupied Bandwidth (Input vs. Output)


Page 1 of 4

Job No.: 0L0367R Date: 04/09/01
Specification: Temperature(°C): 22
Tested By: David Light Relative Humidity(%) 50
E.U.T.: MOR 801Bi Power
Configuration: Transmit iDEN signal
Serial Number: 0013
Location: Lab 1 RBW: Refer to plots
Detector Type: Peak VBW: Refer to plots

Test Equipment Used

Antenna: #N/A Directional Coupler: #N/A
Pre-Amp: #N/A Cable #1: 1082
Filter: #N/A Cable #2: #N/A
Receiver: 1036 Cable #3: #N/A
Attenuator #1: 1065 Cable #4: #N/A
Attenuator #2: 1065 Mixer: #N/A

Additional equipment used:
Measurement Uncertainty: #N/A



Date: 9.APR.2001 10:21:28

Notes: Output signal - iDEN Modulation
Lower bandedge

hi pwr occupied bw iDEN (RETEST)




Dallas Headquarters:
802 N. Kealy
Lewisville, TX 75057
Tel: (972) 436-9600
Fax: (972) 436-2667

KTL Dallas, Inc.

Test Plot: Occupied Bandwidth (Input vs. Output)

Page 2 of 4

Job No.: 0L0367R Date: 4/9/01
Specification: Temperature(°C): 22
Tested By: David Light Relative Humidity(%) 50
E.U.T.: MOR 801Bi Power
Configuration: Transmit iDEN signal



Notes: **Output signal - iDEN Modulation**
Upper bandedge



KTL Dallas, Inc.

Dallas Headquarters:

802 N. Kealy
Lewisville, TX 75057
Tel: (972) 436-9600
Fax: (972) 436-2667

Test Plot: Occupied Bandwidth (Input vs. Output)


Page 3 of 4

Job No.: 0L0367R Date: 04/06/01
Specification: Temperature(°C): 22
Tested By: David Light Relative Humidity(%) 50
E.U.T.: MOR 801Bi
Configuration: Transmit iDEN signal
Serial Number: 0013
Location: #N/A RBW: Refer to plots
Detector Type: #N/A VBW: Refer to plots

Test Equipment Used

Antenna: #N/A Directional Coupler: #N/A
Pre-Amp: #N/A Cable #1: #N/A
Filter: #N/A Cable #2: #N/A
Receiver: #N/A Cable #3: #N/A
Attenuator #1: #N/A Cable #4: #N/A
Attenuator #2: #N/A Mixer: #N/A

Additional equipment used:
Measurement Uncertainty: #N/A



Date: 9.APR.2001 10:23:13

Notes: **Input signal - iDEN Modulation**

hi pwr occupied bandwidth (RETEST)

**Dallas Headquarters:**


802 N. Kealy
Lewisville, TX 75057
Tel: (972) 436-9600
Fax: (972) 436-2667

KTL Dallas, Inc.**Test Plot: Occupied Bandwidth (Input vs. Output)**

Page 4 of 4

Job No.:	0L0367R	Date:	4/6/01
Specification:		Temperature(°C):	22
Tested By:	David Light	Relative Humidity(%):	50
E.U.T.:	MOR 801Bi		
Configuration:	Transmit iDEN signal		

Ref Lvl	Marker 1 [T1]	RBW	200 Hz	RF Att	10 dB
-30.2 dBm	-46.71 dBm	VBW	2 kHz	Mixer	-20 dBm
	868.98750000 MHz	SWT	17.5 s	Unit	dBm



Date: 9.APR.2001 10:30:32

Notes: **Input signal - iDEN Modulation**
Upper bandedge