



16 Photographs – Model ECX13005 Test Setup

16.1 Photograph – Radiation Spurious Emission Test Setup

Below 30MHz Test site 2#



30MHz-1GHz at Test Site 2#



Above 1GHz at Test Site 1#

