Tel 425 882 8080 Fax 425 706 7329 www.microsoft.com



Model 1707 – Internal Photos FCC ID: C3K1707 IC ID: 3048A-1707




Figure 1. Rear of Monitor – Base, Arm Hinge removed

Tel 425 882 8080 Fax 425 706 7329 www.microsoft.com

Microsoft




Figure 2. Hinge Cover removed

Tel 425 882 8080 Fax 425 706 7329 www.microsoft.com

Microsoft




Figure 3. Hinge Cover, antennas removed

Tel 425 882 8080 Fax 425 706 7329 www.microsoft.com

Microsoft




Figure 4. Rear cover of Monitor removed

Tel 425 882 8080 Fax 425 706 7329 www.microsoft.com

Microsoft



Figure 5. Rear cover of Monitor removed

Tel 425 882 8080 Fax 425 706 7329 www.microsoft.com

Microsoft




Figure 6. Shield cans removed from BT/WLAN connectivity board

Tel 425 882 8080 Fax 425 706 7329 www.microsoft.com

Microsoft




Figure 7. Shield cans removed for BT/WLAN connectivity board

Tel 425 882 8080 Fax 425 706 7329 www.microsoft.com

Microsoft




Figure 8. Connectivity Board with BT/WLAN (Close-up)

Tel 425 882 8080 Fax 425 706 7329 www.microsoft.com





Figure 9.WLAN/BT cabling removed

Tel 425 882 8080 Fax 425 706 7329 www.microsoft.com






Figure 10. Chain A (WLAN MIMO)

Tel 425 882 8080 Fax 425 706 7329 www.microsoft.com






Figure 11. Chain B (WLAN Main)

Tel 425 882 8080 Fax 425 706 7329 www.microsoft.com

Microsoft



Figure 12. WLAN MIMO Antenna (Chain A)

Tel 425 882 8080 Fax 425 706 7329 www.microsoft.com

Microsoft



Figure 13. WLAN Main Antenna (Chain B)

Tel 425 882 8080 Fax 425 706 7329 www.microsoft.com






Figure 14. BT/Accessory Radio Antenna