

Prüfbericht - Nr.: 16067943 001
Test Report No.:

Seite 28 von 30
Page 28 of 30

7 Photographs of the Test Set-Up

Photograph 1: Set-up for Radiation Measurement below 1GHz



Prüfbericht - Nr.: 16067943 001
Test Report No.:

Seite 29 von 30
Page 29 of 30

Photograph 2: Set-up for Radiation Measurement above 1GHz

