

Report of Measurements.

Measurements for Radiated Emissions were made in accordance with the procedures and reporting requirements at:

Honeywell's OATS (FCC No: 152762 & IC No:573F-1)
both of which are located at:
2 Corporate Center Drive, Melville, NY 11747

The test report consists of the following exhibits:

REPORT OF MEASUREMENTS (This EXHIBIT) EXHIBIT 5-1
PICTURES OF THE TEST SET UP are found in EXHIBIT 5-2
RADIATED EMISSIONS are recorded in EXHIBIT 5-3
BANDWIDTH MASK is recorded in EXHIBIT 5-4
TEST EQUIPMENT USED is recorded in EXHIBIT 6