


Prüfbericht - Nr.: 12024642 001
Test Report No.:

Seite 70 von 76
Page 70 of 76

6. Photographs of the Test Setup

Photograph 1: Set-up for Conducted Emissions at Antenna Port




Prüfbericht - Nr.: 12024642 001
Test Report No.:

Seite 71 von 76
Page 71 of 76

Photograph 2: Set-up for Frequency Stability, General View



Photograph 3: Set-up for Frequency Stability, inside Temperature Chamber



Produkte
Products


Prüfbericht - Nr.: 12024642 001
Test Report No.:

Seite 72 von 76
Page 72 of 76

Photograph 4: Set-up for Radiated Emissions, Front View



Photograph 5: Set-up for Radiated Emissions, Rear View




Produkte
Products

Prüfbericht - Nr.: 12024642 001
Test Report No.:

Seite 73 von 76
Page 73 of 76

Photograph 6: Set-up for Radiated Emissions, EUT Orientation H



Photograph 7: Set-up for Radiated Emissions, EUT Orientation V

