



**APPENDIX 3: Photographs of test setup**

**Radiated Spurious Emission**  
(Below 1 GHz)



**Photo 1**



**Photo 2**

---

**UL Japan, Inc.**


**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

**Radiated Spurious Emission**  
(Above 1 GHz)



**Photo 1**



**Photo 2**

---

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124

**Worst Case Position**


Below 1 GHz: (Horizontal: X-axis / Vertical: Y-axis)

Above 1 GHz: (Horizontal: X-axis / Vertical: X-axis)

**X-axis**



**Y-axis**



**Z-axis**



**End of Report**