Photo Five Open for Inspection



Photo Nine Close-up of Antenna Connection



Photo Eight Close-up of Transmitter Section with Shielding Removed




Photo Seven Transmitter Section Shielded with Antenna Attachment




Photo Six Inside, Single PCB with Transmitter Section Shielded




Photo Ten Flip Side of PCB, No Components




Photo Eleven Overview of PCB with Antenna

