
Test Report No.: 12914762S-R2

## **APPENDIX3: Photographs of test setup**

## **Radiated Emission**

Front


Rear (below 30 MHz)





Rear (below 1 GHz)

Rear (above 1 GHz)





Test Report No.: 12914762S-R2

## Pre-check of worst case position


EUT Antenna X-axis X-axis







Y-axis Y-axis





Z-axis Z-axis





End of Report