

## Photographs module 99704731

## External

PHOTOGRAPH 1: TOP VIEW OF Y-RAV80	. 2
PHOTOGRAPH 2: BOTTOM VIEW OF Y-RAV80 (BATTERY COMPARTMENT CLOSED)	
PHOTOGRAPH 3: BOTTOM VIEW OF Y-RAV80 (BATTERY COMPARTMENT OPEN)	
PHOTOGRAPH 4: BATTERY COMPARTMENT OF Y-RAV80	

Page: 2 of 5 Report number: 99704731

Photograph 1: Top view of Y-RAV80



Page: 3 of 5 Report number: 99704731

Photograph 2: Bottom view of Y-RAV80 (battery compartment closed)



Page: 4 of 5 Report number: 99704731

Photograph 3: Bottom view of Y-RAV80 (battery compartment open)



Page: 5 of 5 Report number: 99704731

Photograph 4: Battery compartment of Y-RAV80

