



### INTERNAL PHOTOGRAPHS OF EUT













































































## **WLAN Module**












Report No.: T120130G03


Date of Issue: February 3, 2012





### **BT Module**
















#### **WLAN Antenna**











# **Battery**

