



**APPENDIX 3: Photographs of test setup**

**Conducted Emission**

S/N: 10




S/N: 11




### Radiated Spurious Emission


S/N: 10  
Front




S/N: 11  
Front




Rear (below 1 GHz)




Rear (below 1 GHz)



Rear (above 1 GHz)




Rear (above 1 GHz)




**Worst Case Position**


S/N: 10  
X-axis




S/N: 11  
X-axis




Y-axis




Y-axis



Z-axis



Z-axis



**End of Report**