

EXHIBIT F – Internal Photos

FCC ID EJM-HRMP131




Bottom of Radio Board with Shields Installed




Bottom of Radio Board with Shields Removed


Top of Radio Board




Top of System Board




Bottom of System Board



Inside of Front Cover





Inside of Back Cover