

3.3 Configuration Photographs

3.3.1 Conducted Emission Configuration Photographs





Report Number: CWD1015-PC-101608




Worst-case conducted emission, side view



Report Number: CWD1015-PC-101608 Page 12 of 15



3.3.2 Radiated Emission Configuration Photographs



Worst-case radiated emission, rear view

