


APPENDIX 3: Photographs of test setup
Conducted Emission




Radiated Spurious Emission


Front



Rear
Below 1 GHz




Above 1 GHz



Pre-check of Worst Case Position

X-axis



Y-axis



Z-axis



End of Report