



### **APPENDIX 3: Photographs of test setup**

#### **Conducted Emission**




## Radiated Spurious Emission


Front



Rear (Below 1 GHz)




Rear (Above 1 GHz)




### Worst Case Position


Antenna  
X-axis




Y-axis




Z-axis




Module  
X-axis



Y-axis



Z-axis



End of Report