


# INTERTEK TESTING SERVICES

## The Worst Case Configuration Photographs

Radiated Emission – Baby Unit Transmission



Front View



Rear View

# INTERTEK TESTING SERVICES

## The Worst Case Configuration Photographs

AC Conducted Emission – Baby Unit: Play lullaby and mic is ON



Front View



Side View 1

# INTERTEK TESTING SERVICES

---

## The Worst Case Configuration Photographs

AC Conducted Emission



Side View 2